



UNITED STATES PATENT AND TRADEMARK OFFICE

UNITED STATES DEPARTMENT OF COMMERCE
United States Patent and Trademark Office
Address: COMMISSIONER FOR PATENTS
P.O. Box 1450
Alexandria, Virginia 22313-1450
www.uspto.gov

BIBDATASHEET

CONFIRMATION NO. 7999

Bib Data Sheet

SERIAL NUMBER 10/733,213	FILING DATE 12/11/2003 RULE	CLASS 376	GROUP ART UNIT 3641	ATTORNEY DOCKET NO. 12093/929
-----------------------------	---------------------------------------	--------------	------------------------	-------------------------------------

APPLICANTS

George S. Pabis, Lynchburg, VA;

Anthony A. Pugh, Forest, VA;

Raymond A. King, Lynchburg, VA; Darel R. Clark, Lynchburg, VA;

** CONTINUING DATA ***** *None*

** FOREIGN APPLICATIONS ***** *None*

Foreign Priority claimed <input type="checkbox"/> yes <input checked="" type="checkbox"/> no	STATE OR COUNTRY VA	SHEETS DRAWING 3	TOTAL CLAIMS 10	INDEPENDENT CLAIMS 2
35 USC 119 (a-d) conditions met <input type="checkbox"/> yes <input checked="" type="checkbox"/> no <input type="checkbox"/> Met after Allowance	EXAMINER'S SIGNATURE <i>[Signature]</i> Initials			
Verified and Acknowledged				

ADDRESS

26646
KENYON & KENYON
ONE BROADWAY
NEW YORK, NY
10004

TITLE

Fuel assembly top nozzle repair sleeve and method for repairing a fuel assembly

FILING FEE RECEIVED 900	FEES: Authority has been given in Paper No. _____ to charge/credit DEPOSIT ACCOUNT No. _____ for following:	<input type="checkbox"/> All Fees <input type="checkbox"/> 1.16 Fees (Filing) <input type="checkbox"/> 1.17 Fees (Processing Ext. of time) <input type="checkbox"/> 1.18 Fees (Issue) <input type="checkbox"/> Other _____ <input type="checkbox"/> Credit
-----------------------------------	---	---

Credit

10/733213

Examiner: RICHARDSON, JOHN

GAU: 3641

Classification: 376/203.000


Inventor: PABIS, GEORGE, et al

Status: 30 - DOCKETED NEW CASE - READY FOR EXAMINATION

Title: FUEL ASSEMBLY TOP NOZZLE REPAIR SLEEVE AND METHOD FOR REPAIRING A FUEL ASSEMBLY

Bib Data report

Application Title: FUEL ASSEMBLY TOP NOZZLE REPAIR SLEEVE AND METHOD FOR REPAIRING A FUEL ASSEMBLY

Application Num:  (in phx) 10733213 **Filing Date:** 12/11/2003

Effective Filing: 12/11/2003

(Location History) (Foreign/Continuity Data)

Status: 30/DOCKETED NEW CASE - READY FOR EXAMINATION **Status Date:** 04/28/2004

Patent Number: Not Issued **Issue Date:** N/A **Date of Abandonment:** N/A

Confirmation Number: 7999 **PALM Location:**

Examiner: 77495 RICHARDSON, JOHN (Assignment Data) **Group Art Unit:** 3641 **Class/Subclass:** 376/203.000

State or Country: VIRGINIA **Sheets/Drawing:** 3 **Total Claims:** 10
Independent Claims: 2



Inventors:

Last name, First name:	City:	Country or State:
------------------------	-------	-------------------

<u>PABIS, GEORGE</u>	LYNCHBURG	VIRGINIA
----------------------	-----------	----------

<u>PUGH, ANTHONY</u>	FOREST	VIRGINIA
----------------------	--------	----------

<u>KING, RAYMOND</u>	LYNCHBURG	VIRGINIA
----------------------	-----------	----------

<u>CLARK, DAREL</u>	LYNCHBURG	VIRGINIA
---------------------	-----------	----------

Attorneys: ALL **Attorney Docket No:** 12093/929

Interference No: **Lost Case:** No **Unmatched Petition:** No **L&R Code:** 3